# QUALITY CONTROL

BR No: 158/13-14 dt 31-5-2013

Name of the Work: Providing Cement concrete to Cross roads at Backside of Mahalakshmi temple Kalyananagar in Ward No-13 in SSD

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.

Assistance Executive Engineer
Shetty Halli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike